STERET

OUT56244

23 JUL 1965

Office

File OS

ADMIN STC DR

C80

1. 3 F2

PSO I Su-IUD TIO

PID

PAG DIAXX-4

SPAD NSA-LO

DIA-AP

Act.

COPIES RECFIVED_

Cy No.

P 221945Z
FM NPIC WASHDC
TO RUCSC/SAC OFFUTT AFB OMAHA NEB
RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
RUCVAA/2D RTS BARKSDALE AFB LA
RUEKDA/DIA WASHDC
RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
RUEPIA/CIA WASHDC
RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
RUWGAA/2AF BARKSDALE AFB LA
BT

1865 dul 21 20 15**7**

Declassification Review by NGA/DoD

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

- 1. CAMERA B 23 WAS USED IN MISSION 8031 FLOWN ON 20 JULY
- 1965. PROCESSING WAS ACCOMPLISHED BY BARKSDALE.
 - 2. ORIGINAL NEGATIVE:

TO 2638.

S E C R E T CITE NPIC 5020.

- A. EXPOSURE WAS ADEQUATE AND RESOLUTION WAS GOOD.
- B. 9R SIDE: PRESSURE ROLLER STATIC (ROLLER CHATTER) IS
 PRESENT ALONG BOTH EDGES THROUGHOUT THE MISSION. PLUS DENSITY
 CIRCULAR SPOTS APPROXIMATELY Ø.5" DIAMETER ARE SPACED ABOUT
 5.Ø" APART IN THE FIRST 3ØØ FRAMES 1.Ø" FROM THE OUTBOARD EDGE.
 AFTER FRAME 3ØØ THESE SPOTS APPEAR INTERMITTENTLY AND ARE IRREGULARLY SPACED TO FRAME 375. FOR THE REMAINDER OF THE MISSION
 THE PLUS DENSITY SPOTS APPEAR INTERMITTENTLY ALONG THE TITLED
 MARGIN OF THE FILM. OUTBOARD EDGE STATIC EXISTS FROM FRAME 9ØØ

A MANUFACTURING SPLICE WITH ASSOCIATED FOGGING IS PRESENT IN FRAME 1561. A BREAKDOWN HEAT SPLICE EXISTS BETWEEN FRAMES 1789 AND 1790.

Excines 1944 88021 **Gen** 1950 1968 858



OUTBOARD EDGE SCALLOPING OCCURS IN FRAMES 1200 TO 1225.

- C. 9L SIDE: EDGE STATIC IS PRESENT ON BOTH EDGES OF THE FILM. ROLLER CHATTER APPEARS ON THE INBOARD EDGE THROUGHOUT THE MISSION BUT IS ONLY INTERMITTENT ON THE OUTBOARD EDGE.

 THERE IS A HEAT SPLICE BETWEEN FRAMES 1824/1825 AND A MANUFACTURING SPLICE IN FRAME 1829. A FILM TRACKING PROBLEM WHICH PROBABLY OCCURRED DURING PROCESSING IS APPARENT IN FRAMES 2108 THROUGH 2118. THE RESULTS ARE PROCESSING STREAKS, CREASES, AND CRIMPS APPROXIMATELY 0.5" APART ALONG THE TITLED EDGE OF THE FILM.
 - D. THE LAST TITLED FRAME ON BOTH SIDES IS 2638.
 - E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.
 - 3. POSITIVE:
 - A. PI SUITABILITY IS GOOD.
 - B. PRINTING AND PROCESSING IS ADEQUATE.
 - C. CLOUD COVER IS APPROXIMATELY 20 PERCENT.

GP-1.

SECRET

-END OF MESSAGE-